

FIG. 5




FIG. 6

702

704

706

708

Home | Menu | Selection | Exception Header | Help

Ln	Car Init	Car Num	Kind of Car	Repair Date	Repaired At	Road   Date	Ref Nbr	Acct Dt	Bill Rd
1	ASOX	051146	B - BOX	2/1/2001	123456 - CHICAGO		711234	2001 - 02	DTLR

Ln	Attach	Lc	Qty	C	AJob/QF	Description	MO	YR	MF	C	AS	AF	R5	RF	WM	RJob/QF	R	Net Chg								
2	NONE	1	7	1143	00	SINGLE CAR APT, W/O BRAKE CYL TA										21	1143	00	1	\$67.24						
3	NONE	1	3	1581	00	ABOW EMERG. PORT. CLEARED &/OR R										12	1301	80	1	\$202.76						
4	NONE	6	1	1840	00	BRAKE SHOE-COMP, HI-FRCT 2 IN.										01	1840	00	1	\$82.20						
5	NONE	1	1	1852	00	BRAKE SHOE KEY										01	1852	00	1	\$7.33						
6	NONE	0	1	2161	00	CARRIER WEAR FLT./STRIKER SHOM (										02	2161	00	1	\$26.53						
7	M&I Dup Oth	A	1	1	4458	00	LABOR, JACK CAR									09	4458	00	1	\$57.24						
8	NONE	1	1	4624	QY	STENCIL, CONSOLIDATED-PER SIDE										22	4624	QY	1	\$38.46						
																		<b>Total Charge</b>								<b>\$481.76</b>

Ln	Attach	Exception Message	Excp Amt	RR Action
7	M&I Dup Oth	No justification to jack car.	\$57.24	NOT PROCESSED
Comments:				

BRC 2 of 331

Copyright © 2001 TTX Company. All rights reserved.

FIG. 7

800

802

804

Attachment Files

DTLR

051146\_0000124355000002.PDF

Exception Document Attachment

Billing Road

Owner Initial

Account Date

Billing Road Suffix

Car Initial

Car Number

SPLC

Repair Date

Line Number

Path:

Back Attach

Copyright © 2001 TTX Company. All rights reserved.

FIG. 8




FIG. 9